Executive Summary – Enforcement Matter – Case No. 46121 Valero Refining-Texas, L.P. RN100211663 Docket No. 2013-0248-IWD-E

Order Type:

1660 Agreed Order

Findings Order Justification:

N/A

Media:

IWD

Small Business:

No

Location(s) Where Violation(s) Occurred:

Valero Corpus Christi Refinery East Plant, located at 1300 Cantwell Lane, east of Navigation Boulevard, and approximately 0.5 mile north of IH-37, northwest of Corpus Christi, Nueces County

Type of Operation:

Petroleum refinery

Other Significant Matters:

Additional Pending Enforcement Actions: No

Past-Due Penalties: No

Other: N/A

Interested Third-Parties: None

Texas Register Publication Date: July 26, 2013

Comments Received: No

Penalty Information

Total Penalty Assessed: \$8,438

Amount Deferred for Expedited Settlement: \$1,687 Amount Deferred for Financial Inability to Pay: \$0

Total Paid to General Revenue: \$6,751 **Total Due to General Revenue:** \$0

Payment Plan: N/A

SEP Conditional Offset: \$0

Name of SEP: N/A

Compliance History Classifications:

Person/CN - Satisfactory Site/RN - Satisfactory

Major Source: Yes

Statutory Limit Adjustment: N/A

Applicable Penalty Policy: September 2011

Executive Summary – Enforcement Matter – Case No. 46121 Valero Refining-Texas, L.P. RN100211663 Docket No. 2013-0248-IWD-E

Investigation Information

Complaint Date(s): N/A

Complaint Information: N/A

Date(s) of Investigation: November 6, 2012

Date(s) of NOE(s): January 11, 2013

Violation Information

Failed to prevent the unauthorized discharge of contaminated storm water into or adjacent to any water in the state. Specifically, on April 16, 2012, to prevent the overflow from the surge tank, an estimated 561,000 gallons of contaminated storm water was pumped to an earthen containment area surrounding Tank 201 [30 Tex. Admin. Code § 305.125(4), Tex. Water Code § 26.121(a)(1), and Texas Pollutant Discharge Elimination System Permit No. WQ0000465000, Permit Conditions No. 2.g].

Corrective Actions/Technical Requirements

Corrective Action(s) Completed:

Respondent has implemented the following corrective measures:

- a. By March 21, 2012, initiated a project to convert Tank 202 into a storm water tank;
- b. By April 20, 2012, removed, treated, tested, and properly disposed of contaminated soil and contaminated storm water from the affected area; and
- c. By November 8, 2012, converted Tank 202 into a storm water tank to hold contaminated storm water to prevent further overflows of the surge tank.

Technical Requirements:

N/A

Litigation Information

Date Petition(s) Filed: N/A Date Answer(s) Filed: N/A SOAH Referral Date: N/A Hearing Date(s): N/A Settlement Date: N/A

Executive Summary – Enforcement Matter – Case No. 46121 Valero Refining-Texas, L.P. RN100211663 Docket No. 2013-0248-IWD-E

Contact Information

TCEQ Attorney: N/A

TCEQ Enforcement Coordinator: Heather Brister, Enforcement Division,

Enforcement Team 1, MC R-09, (254) 761-3034; Candy Garrett, Enforcement Division,

MC 219, (512) 239-1456

TCEQ SEP Coordinator: N/A

Respondent: Dennis Payne, Vice-President & General Manager, Valero Refining-

Texas, L.P., P.O. Box 9370, Corpus Christi, Texas 78469

Respondent's Attorney: N/A

Penalty Calculation Worksheet (PCW) Policy Revision 3 (September 2011) PCW Revision August 3, 2011 Assigned 14-Jan-2013 **EPA Due** PCW 29-Jan-2013 Screening 28-Jan-2013 RESPONDENT/FACILITY INFORMATION Respondent Valero Refining-Texas, Reg. Ent. Ref. No. RN100211663 Facility/Site Region 14-Corpus Christi Major/Minor Source Major CASE INFORMATION Enf./Case ID No. 46121 Docket No. 2013-0248-IWD-E Media Program(s) Water Quality No. of Violations 1 Order Type 1660 Government/Non-Profit No Multi-Media Enf. Coordinator Heather Brister EC's Team Enforcement Team 1 Admin. Penalty \$ Limit Minimum \$25,000 Maximum

		Pena	Ity Calculation Section		
TOTAL BASE PENA	ALTY (S			Subtotal 1	\$3,750
ADJUSTMENTS (+ Subtotals 2-7 are o	/-) TO btained by n	SUBTOTAL 1 nultiplying the Total Ba	se Penalty (Subtotal 1) by the indicated percen	itage.	72
Compliance H			100.0% Enhancement	Subtotals 2, 3, & 7	\$3,750
Notes	dissimi	ar violations, four denial of liability.	NOV with similar violations, two NOVs orders with denial of liability, and two Reduction for five Notices of Intent to d two disclosures of violations.	oorders	
Culpability	No		0.0% Enhancement	Subtotal 4	\$0
Notes		The Respondent d	does not meet the culpability criteria.		
Good Faith Eff	ort to Co	mply Total Adjus	stments .	Subtotal 5	\$937
Economic Ben	efit Total EB /	Amounts \$73,524	50.0% Enhancement* *Capped at the Total EB \$ Amou.	Subtotal 6	\$1,875
Approx	. Cost of Cor	npliance \$1,935,000			
SUM OF SUBTOTA	LS 1-7			Final Subtotal	\$8,438
OTHER FACTORS A Reduces or enhances the Fina				Adjustment	\$0
Notes					
				Final Penalty Amount	\$8,438
STATUTORY LIMI	T ADJUS	STMENT	Fil	nal Assessed Penalty	\$8,438
DEFERRAL Reduces the Final Assessed Re	analty by the	indicted accounts as	20.0% Re	duction Adjustment	-\$1,687
	stratey by the				
Notes		Deferral off	ered for expedited settlement.		
PAYABLE PENALT	Y				\$6,751

Screening Date 28-Jan-2013

Respondent Valero Refining-Texas, L.P.

Case ID No. 46121

Reg. Ent. Reference No. RN100211663

Media [Statute] Water Quality Enf. Coordinator Heather Brister

Policy Revision 3 (September 2011) PCW Revision August 3, 2011

PCW

Compliance History Worksheet

Component	Number of	Enter Number Here	Adjust
NOVs	Written notices of violation ("NOVs") with same or similar violations as those in the current enforcement action (number of NOVs meeting criteria)	1	5%
	Other written NOVs	2	4%
	Any agreed final enforcement orders containing a denial of liability (number of orders meeting criteria)	4	80%
Orders	Any adjudicated final enforcement orders, agreed final enforcement orders without a denial of liability, or default orders of this state or the federal government, or any final prohibitory emergency orders issued by the commission		50%
Judgments and Consent	Any non-adjudicated final court judgments or consent decrees containing a denial of liability of this state or the federal government (number of judgements or consent decrees meeting criteria)	0	0%
Decrees	Any adjudicated final court judgments and default judgments, or non-adjudicated final court judgments or consent decrees without a denial of liability, of this state or the federal government	0	0%
Convictions	Any criminal convictions of this state or the federal government (number of counts)	0	0%
Emissions	Chronic excessive emissions events (number of events)	0	0%
Audits	Letters notifying the executive director of an intended audit conducted under the Texas Environmental, Health, and Safety Audit Privilege Act, 74th Legislature, 1995 (number of audits for which notices were submitted)	5	-5%
	Disclosures of violations under the Texas Environmental, Health, and Safety Audit Privilege Act, 74th Legislature, 1995 (<i>number of audits for which violations were disclosed</i>)	2	-4%
	Ple	ase Enter Yes or No	
	Environmental management systems in place for one year or more	No	0%
Other	Voluntary on-site compliance assessments conducted by the executive director under a special assistance program	No	0%
	Participation in a voluntary pollution reduction program	No	0%
	Early compliance with, or offer of a product that meets future state or federal government environmental requirements	No	0%
	Adjustment Per	centage (Sub	total 2)
eat Violator (No		rentage (Subi	total 3
		cemage (oub.	otai 5)
	pry Person Classification (Subtotal 7)	(Cb-	
Satisfactory		centage (Subt	otal /)
npliance Histo	ry Summary		
Compliance History Notes	Enhancement for one NOV with similar violations, two NOVs with dissimilar violation with denial of liability, and two orders without denial of liability. Reduction for fixed intent to conduct an audit and two disclosures of violations.	BENDANDER SICKER FOR STANDARD	
	Total Compliance History Adjustment Percentage (S	Subtotals 2, 3	3, & 7)
	listory Adjustment		

	ening Date		Docket No. 2013-0248-IWD-E	PC	CW
		Valero Refining-Texas, L.	Р.	Policy Revision 3 (September 2	2011)
A restriction of the contract	ase ID No.			PCW Revision August 3, .	2011
Reg. Ent. Ref					
		Water Quality			
§ 1. The second of the Administration of		Heather Brister			
Viola	tion Number		205 125(4) Toy Water Code 5 26 121(a)(1)	= 	1
To constitute ou	Rule Cite(s)	Pollutant Discharge F	305.125(4), Tex. Water Code § 26.121(a)(1), a Elimination System Permit No. WQ0000465000,	Permit	
900000000000000000000000000000000000000		Tonatant Discharge L	Conditions No. 2.g		
		_ , , , , , , , , , , , , , , , , , , ,			00000
Violation	n Description	adjacent to any wate conducted on Novembe overflow from the surge t	authorized discharge of contaminated storm wat er in the state, as documented during an investi- er 6, 2012. Specifically, on April 16, 2012, to pre- tank, an estimated 561,000 gallons of contamina o an earthen containment area surrounding Tan	gation event the ated storm	
400A1004000400040004000400040004000400040			Bas	e Penalty \$25,	,000
>> Environmen	stal Proper	ty and Human Heal	th Matrix		dragon and a
// Littlionimen	ital, Fropei	Harm			
	Release	Major Moderat	te Minor		
OR	Actual		x		
	Potential		Percent 15.0%		-
>> Drog-rame	ic Matrix				100000000000000000000000000000000000000
>>Programmat	Falsification	Major Moderat	te Minor		-
			Percent 0.0%		
Q.					0.000
	Human healt	h or the environment has i	been exposed to insignificant amounts of polluta	nts which	
Matrix Notes	do not exceed	levels that are protective	of human health or environmental receptors as	a result of	
Notes			the violation.		4
			Adjustment	\$21,250	
Professional Park				\$3,	,750
Violation Events	S				***************************************
No. of the second secon	Mumahan of I	Violetian Events	Mumber of violation	dave	all to be
	Number of	Violation Events 1	4 Number of violation	uays	
	mark only one with an x	daily weekly monthly quarterly semiannual annual single event	Violation Bas	a Penalty \$3,	,750
and a supplemental	One guardant	, avent is recommended for	rom the date of the discharge (April 16, 2012) to	the date	No.
***************************************	one quarter		harge was cleanded up (April 20, 2012).	uno detto	***************************************
7000-1079999					
Good Faith Effo	rts to Com	ply 25.0	0% Reduction	\$	937
		Before NO		<u> </u>	
ren-and production		Extraordinary			
no establishment		Ordinary x			URANO PRO 1
and the second		N/A	(mark with x)		
CONTROL CONTRO		Notes The Res	pondent achieved compliance on November 8, 2012.		Also de Alliformacione parameters
**************************************					075
Essential Parameter	fit (FD) f-	Shir wateria	Violation Statutony Limit		,813
Economic Bene		ed EB Amount	\$73,524 Violation Final Pena		,438
Paradicina terrational terrati		1	riolation Final Assessed Penalty (adjusted for	-	,438

	E	conomic	Benefit	Wo	rksheet	100.0	
Respondent Case ID No. Reg. Ent. Reference No.	46121	,	-		etat 1 seks - varrinkst solge var planten på et en et en seks et en et et en et en et en et en et en et en et	mist employed (mysphingmath the experience of the experience of the experience copies of the post flow).	
HT.	Water Quality					Percent Interest	Years of Depreciation
						5.0	15
	Item Cost	Date Required	Final Date	Yrs	Interest Saved	Onetime Costs	EB Amount
Item Description	No commas or \$	nak a samu sa					
Delayed Costs							
Equipment	Cyrellogic February Long			0.00	\$0	\$0	\$0
Buildings				0.00	\$0	\$0	\$0
Other (as needed)				0.00	\$0	\$0	\$0
Engineering/construction	\$1,860,000	16-Apr-2012	8-Nov-2012	0.56	\$3,499	\$69,984	\$73,483
Land				0.00	\$0	n/a	\$0
Record Keeping System				0.00	\$0	n/a	\$0
Training/Sampling				0.00	\$0	n/a	\$0
Remediation/Disposal	\$75,000	16-Apr-2012	20-Apr-2012	0.01	\$41	n/a	\$41
Permit Costs				0.00	\$0	n/a	\$0
Other (as needed)				0.00	\$0	n/a	\$0
Notes for DELAYED costs		from the affected	l area. Date re	quired		ntaminated soil and n date. Final dates : llance.	
Avoided Costs	ANNUAL	IZE [1] avoided	costs before	enterir	ng item (except	for one-time avoid	led costs)
Disposal				0.00	\$0	\$0	\$0
Personnel				0.00	\$0	\$0	\$0
Inspection/Reporting/Sampling				0.00	\$0	\$ 0	\$0
Supplies/equipment	Estantiske Kalton			0.00	\$0	\$0	\$0
Financial Assurance [2]				0.00	\$0	\$0	\$0
ONE-TIME avoided costs [3]				0.00	\$0	\$0	\$0
Other (as needed)				0.00	\$0	\$0 l	\$0
Notes for AVOIDED costs							
Approx. Cost of Compliance		\$1,935,000			TOTAL		\$73,524



ŒQ Compliance History Report

PUBLISHED Compliance History Report for CN600127468, RN100211663, Rating Year 2012 which includes Compliance History (CH) components from September 1, 2007, through August 31, 2012.

Customer, Respondent, CN600127468, Valero Refining-Texas, L.P. Classification: SATISFACTORY

Rating: 11.61

or Owner/Operator:

Regulated Entity:

RN100211663, VALERO CORPUS CHRISTI REFINERY EAST PLANT

Classification: SATISFACTORY

Rating: 9.45

Complexity Points:

43

Repeat Violator: NO

CH Group:

02 - Oil and Petroleum Refineries

Location: 1300 CANTWELL LN, EAST OF NAVIGATION BOULEVARD, AND APPROXIMATELY 0.5 MILE NORTH OF

INTERSTATE HIGHWAY 37, NORTHWEST OF CORPUS CHRISTI, NUECES COUNTY, TEXAS

TCEQ Region:

REGION 14 - CORPUS CHRISTI

ID Number(s):

AIR OPERATING PERMITS ACCOUNT NUMBER NE0043A

AIR OPERATING PERMITS PERMIT 2238

INDUSTRIAL AND HAZARDOUS WASTE PERMIT 50261

INDUSTRIAL AND HAZARDOUS WASTE EPA ID

TXD008132268

WASTEWATER PERMIT WQ0000465000

AIR NEW SOURCE PERMITS REGISTRATION 71884

AIR NEW SOURCE PERMITS PERMIT 1084 **AIR NEW SOURCE PERMITS PERMIT 2937**

AIR NEW SOURCE PERMITS PERMIT 11456

AIR NEW SOURCE PERMITS REGISTRATION 13764

AIR NEW SOURCE PERMITS REGISTRATION 21563

AIR NEW SOURCE PERMITS REGISTRATION 41936 AIR NEW SOURCE PERMITS AFS NUM 4835500018

AIR NEW SOURCE PERMITS EPA PERMIT PSDTX1023M1

AIR NEW SOURCE PERMITS REGISTRATION 78472

AIR NEW SOURCE PERMITS REGISTRATION 87486 AIR NEW SOURCE PERMITS EPA PERMIT PSDTX1023M2

AIR NEW SOURCE PERMITS REGISTRATION 95585

AIR NEW SOURCE PERMITS EPA PERMIT PSDTX1023M3 **AIR NEW SOURCE PERMITS REGISTRATION 102329**

AIR NEW SOURCE PERMITS REGISTRATION 107521

IHW CORRECTIVE ACTION SOLID WASTE REGISTRATION

(SWR) 30530

AIR EMISSIONS INVENTORY ACCOUNT NUMBER NE0043A

AIR OPERATING PERMITS PERMIT 1231

AIR OPERATING PERMITS PERMIT 2250

INDUSTRIAL AND HAZARDOUS WASTE SOLID WASTE

REGISTRATION # (SWR) 30530

INDUSTRIAL AND HAZARDOUS WASTE EPA ID

TXD063085567

WASTEWATER EPA ID TX0006904

AIR NEW SOURCE PERMITS ACCOUNT NUMBER NE0043A

AIR NEW SOURCE PERMITS PERMIT 1085 AIR NEW SOURCE PERMITS PERMIT 10923

AIR NEW SOURCE PERMITS REGISTRATION 11652

AIR NEW SOURCE PERMITS PERMIT 2180A

AIR NEW SOURCE PERMITS PERMIT 22390

AIR NEW SOURCE PERMITS REGISTRATION 75588 AIR NEW SOURCE PERMITS REGISTRATION 72781

AIR NEW SOURCE PERMITS EPA PERMIT PSDTX1023

AIR NEW SOURCE PERMITS REGISTRATION 78481

AIR NEW SOURCE PERMITS REGISTRATION 84566

AIR NEW SOURCE PERMITS REGISTRATION 92232

AIR NEW SOURCE PERMITS REGISTRATION 101544

AIR NEW SOURCE PERMITS REGISTRATION 99899

AIR NEW SOURCE PERMITS REGISTRATION 101863

AIR NEW SOURCE PERMITS REGISTRATION 105635

WASTEWATER LICENSING LICENSE WQ0000465000

POLLUTION PREVENTION PLANNING ID NUMBER

P01014

Compliance History Period: September 01, 2007 to August 31, 2012 Rating Year: 2012 **Rating Date:** 09/01/2012

Date Compliance History Report Prepared: March 20, 2013

Agency Decision Requiring Compliance History: Enforcement

Component Period Selected: March 20, 2008 to March 20, 2013

TCEQ Staff Member to Contact for Additional Information Regarding This Compliance History.

Name: Heather Brister Phone: (254) 761-3034

Site and Owner/Operator History:

1) Has the site been in existence and/or operation for the full five year compliance period?

YES

2) Has there been a (known) change in ownership/operator of the site during the compliance period?

NO

3) If YES for #2, who is the current owner/operator?

N/Δ

4) If YES for #2, who was/were the prior

N/A

owner(s)/operator(s)?

5) If **YES**, when did the change(s) in owner or operator N/A

occur?

1

2

Components (Multimedia) for the Site Are Listed in Sections A - J

A. Final Orders, court judgments, and consent decrees:

Effective Date: 04/14/2008 ADMINORDER 2007-1189-AIR-E (1660 Order-Agreed Order With Denial)

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 116, SubChapter G 116.715(a)

5C THC Chapter 382, SubChapter D 382.085(b)

Rqmt Prov:No.: 2937 PERMIT

PSD-TX-1023M1 PERMIT

Description: This permit authorizes emissions only from those points listed in the attached table entitled "Emission Sources - Emission Caps and Individual Emission Limitations".

Effective Date: 11/17/2008 ADMINORDER 2007-1545-AIR-E (1660 Order-Agreed Order With Denial)

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter F 101.211(b)(1)(H)

30 TAC Chapter 101, SubChapter F 101.211(b)(1)(I)

5C THC Chapter 382, SubChapter D 382.085(b)

Description: Failed to submit an administratively complete final report within two weeks after the end of the activity. Specifically, the Respondent failed to individually list all compounds or mixtures of air contaminants involved in the emissions activity, their estimated total quantities, the authorized emissions limits for those contaminants, and the preconstruction authorization in the final report for Incident Number 87955.

Classification: Major

Citation: 30 TAC Chapter 116, SubChapter G 116.715(a)

5C THC Chapter 382, SubChapter D 382.085(b)

Rqmt Prov:TCEQ Air Permit 2937/PSD-TX-1023MI PERMIT

Description: Failed to prevent unauthorized emissions. Specifically, the Respondent released 63.38 lbs of benzene, 2,173.93 lbs of VOCs, 67.95 lbs of toluene, 19.5 lbs of xylene and 6.3 lbs of ethylbenzene during a maintenance activity involving Tank 102 that began March 6, 2007 and lasted 24 hours.

3 Effective Date: 08/23/2009 ADMINORDER 2007-1813-MLM-E (Findings Order-Agreed Order Without Denial)

Classification: Major

Citation: 30 TAC Chapter 335, SubChapter C 335.69(a)(1)(B)

Description: Failure to comply with hazardous waste tank requirements.

Classification: Major

Citation: 2D TWC Chapter 26, SubChapter A 26.121(a)

30 TAC Chapter 335, SubChapter A 335.4

30 TAC Chapter 335, SubChapter B 335.43(a)

Description: Failure to prevent the unauthorized discharge of untreated industrial wastewater and contact storm water from Tank 109 to the tank containment area and the discharge of oil from Tank 100 and allowing it to mix with the accumulated storm water inside the tank containment area.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 116, SubChapter G 116.715(a)

5C THSC Chapter 382 382.085(b)

Rqmt Prov:SC 18 PERMIT

Description: Failure to maintain particulate matter emissions on Complex 8 FCCU (EPN 12-CO-STK) at or below the permitted limit of one pound per 1,000 pounds coke burn-off. An emission rate of 1.08 pounds per 1,000 pounds coke burn-off was documented during a performance test conducted on August 15, 2007.

4 Effective Date: **09/21/2009** ADMINORDER 2009-0288-AIR-E (Findings Order-Agreed Order Without Denial)

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter G 116.715(a)

5C THSC Chapter 382 382.085(b)

Ramt Prov: Special Condition 1 PERMIT

Description: Failed to prevent unauthorized emissions. Specifically, the Respondent released 59,497 lbs of CO, 1,509.61 lbs of SO2, 849.14 lbs of PM, 136 lbs of NOx, 131.71 lbs of H2SO4 and 20.23 lbs of VOCs from the Fluid Catalytic Cracking Unit during an avoidable emissions event that began May 18, 2008 and lasted 10 hours and 48 minutes. A differential pressure indicator became plugged with catayst and mistakenly indicate an eroneous pressure reading, resulting in a

reversal of hot oil and catalyst

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 116, SubChapter G 116.715(c)(7) 30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rqmt Prov: Special Condition No. 1 PERMIT

STC No. 21 OP

Description: Failed to prevent unauthorized emissions. Specifically, the Respondent released 723.15 lbs of SO2, 7.38 lbs H2S, 6.09 lbs of CO, 0.84 lbs of NOx and 8.39 lbs of VOCs from the Vacuum Unit during a foreseeable emissions event (Incident No. 112938) that began August 21, 2008 and lasted 48 minutes.

Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter F 101.201(b)(1)(D)

30 TAC Chapter 101, SubChapter F 101.201(b)(1)(G)

30 TAC Chapter 101, SubChapter F 101.201(b)(1)(H)

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rqmt Prov:2238 - SC No. (2)(F) OP

Description: Failed to submit an administratively complete final report for Incident No. 113325. Specifically, the Respondent failed to list the compounds released from Tail Gas Unit Incinerator No. 1 and the total quantities of air contaminants released during the event

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 116, SubChapter G 116.715(c)(7)

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rqmt Prov: 2238 -SC Nos. 21 & 23 OP

Flexible Permit No. 2937 - SC No. 1 PERMIT

Description: Failed to prevent unauthorized emissions. Specifically, the Respondent released 1,036.1 lbs of SO2, 6.33 lbs hydrogen sulfide ("H2S"), 1.38 lbs of CO, 1.17 lbs of sulfur, 0.42 lbs of carbonyl sulfide, 0.27 lbs of NOx and 0.27 lbs of carbon disulfide from the Sulfur Recovery Unit during an avoidable emissions event (Incident No. 113325) that began August 30, 2008 and lasted 43 minutes. The unauthorized release was the result of a fuel gas valve malfunction resulting in the shutdown of the feed

5 Effective Date: 12/18/2009 ADMINORDER 2009-0510-AIR-E (1660 Order-Agreed Order With Denial)

Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter F 101.201(b)

30 TAC Chapter 101, SubChapter F 101.201(c)

5C THSC Chapter 382 382.085(b)

Description: Failed to submit the final report for Incident No. 116693 in timely manner. Specifically, the report was due November 30, 2008 and submitted on December 1, 2008.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(1)

30 TAC Chapter 101, SubChapter A 101.20(2)

30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 113, SubChapter C 113.120

30 TAC Chapter 116, SubChapter G 116.715(a)

30 TAC Chapter 122, SubChapter B 122.143(4)

40 CFR Chapter 60, SubChapter C, PT 60, SubPT Kb 60.112b(a)(1)(i)

40 CFR Chapter 60, SubChapter C, PT 60, SubPT Kb 60.112b(a)(1)(iv)

40 CFR Chapter 61, SubChapter C, PT 61, SubPT FF 61.351(a)(1)

40 CFR Chapter 63, SubChapter C, PT 63, SubPT G 63.119(b)(1)

40 CFR Chapter 63, SubChapter C, PT 63, SubPT G 63.119(b)(6)

40 CFR Chapter 63, SubChapter C, PT 63, SubPT G 63.133(a)(2)(ii)

5C THSC Chapter 382 382.085(b)

Rqmt Prov:[2937/PSD-TX-1023M1] Special Condition 1 PERMIT

Permit O-2250, Spec. Terms & Cond. No. 1 OP

Description: Failed to prevent unauthorized emissions. Specifically, the Respondent released 338.32 lbs of VOCs, 21.87 lbs of benzene, 13.34 lbs of toluene, 12.24 lbs of H2S, 5.22 lbs of xylene and 1.23 lbs ethylbenzene during an avoidable emissions event (Incident No. 116871) that began November 19, 2008 and lasted 45 hours. The unauthorized release was the result of a failure to bolt or fasten covers on each access hatch to form an air-tight seal on Tank 9. Since there was no air tight seal, benzene water

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 116, SubChapter G 116.715(a)

5C THSC Chapter 382 382.085(b)

Rqmt Prov:[2937/PSD-TX-1023M1] Special Condition 1 PERMIT

Description: Failed to prevent unauthorized emissions. Specifically, the Respondent released 3,669.45 lbs of SO2, 39.78 lbs of H2S, 4.59 lbs of CO, 0.90 lbs of NOx, 0.16 lbs of VOCs and 0.04 lbs of ammonia during an emissions event (Incident No. 116693) that began November 16, 2008 and lasted 48 minutes. The unauthorized release was the result of an electronic component malfunction that caused the acid gas feed control valve to malfunction. Because the final report for this emissions event was submitted late

6 Effective Date: 11/18/2011 ADMINORDER 2010-0909-MLM-E (1660 Order-Agreed Order With Denial)

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 116, SubChapter G 116.715(a)

5C THSC Chapter 382 382.085(b)

Rqmt Prov:Permit 2937, Special Condition 10.A. PERMIT

Description: Failed to comply with the 0.035 lb of NOx per million British thermal units ("lb NOx/MMBtu") on an hourly averaging period for Boiler Nos. 1, 2 and 5, as reported in the semi-annual deviation reports for the annual compliance certification periods of November 24, 2007 through November 23, 2008 and November 24, 2008 through November 23, 2009 at the Corpus Christi Refinery East Plant.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 116, SubChapter G 116.715(a)

5C THSC Chapter 382 382.085(b)

Rqmt Prov:Flexible Permit 2937, SC 1 PERMIT

Description: Failed to prevent unauthorized emissions at the Corpus Christi Refinery East Plant.

B. Criminal convictions:

N/A

C. Chronic excessive emissions events:

N/A

D. The approval dates of investigations (CCEDS Inv. Track. No.):

The approv	al dates of investigatio	
Item 1	March 31, 2008	(640957)
Item 2	April 08, 2008	(636416)
Item 3	April 14, 2008	(641040)
Item 4	April 18, 2008	(690060)
Item 5	May 05, 2008	(654417)
Item 6	May 21, 2008	(690061)
Item 7	May 23, 2008	(680306)
Item 8	May 28, 2008	(671660)
Item 9	May 30, 2008	(641327)
Item 10	May 31, 2008	(532287)
Item 11	June 10, 2008	(641355)
Item 12	June 12, 2008	(636082)
Item 13	June 16, 2008	(690062)
Item 14	July 17, 2008	(710843)
Item 15	August 20, 2008	(688327)
Item 16	August 25, 2008	(710844)
Ítem 17	September 18, 2008	(710845)
Item 18	October 09, 2008	(704922)
Item 19	October 22, 2008	(727556)
Item 20	October 31, 2008	(705894)
Item 21	December 03, 2008	(708988)
Item 22	December 15, 2008	(720987)
Item 23	December 16, 2008	(727559)
Item 24	December 22, 2008	(709272)
Item 25	January 21, 2009	(750372)
Item 26	February 19, 2009	(768431)
Item 27	February 25, 2009	(735573)
Item 28	March 27, 2009	(750371)
Item 29	April 08, 2009	(740281)
Item 30	April 22, 2009	(768432)
Item 31	April 30, 2009	(742256)
Item 32	May 21, 2009	(768433)
Item 33	June 09, 2009	(747146)
Item 34	June 10, 2009	(746935)
Item 35	June 22, 2009	(748756)
Item 36	July 09, 2009	(749787)
Item 37	July 20, 2009	(924852)
Item 38	August 02, 2009	(761871)
Item 39	August 20, 2009	(924853)
Item 40	September 05, 2009	(739607)
Item 41	September 22, 2009	(924854)
Item 42	October 06, 2009	(777079)
Item 43	October 14, 2009	(779041)
Item 44	October 19, 2009	(924855)
Item 45	November 17, 2009	(782605)
Item 46	November 23, 2009	(924856)
Item 47	December 03, 2009	(783645)
Item 48	December 21, 2009	(924857)
Item 49	January 19, 2010	(785428)
Item 50	January 20, 2010	(788420)
Item 51	January 27, 2010	(789406)
Item 52	January 28, 2010	(789587)
Item 53	February 18, 2010	(792451)
Item 54	February 19, 2010	(792055)
Item 55	February 26, 2010	(793930)
Item 56	March 22, 2010	(830974)
Item 57	March 25, 2010	(796350)
Item 58	April 21, 2010	(830975)
Item 59	May 20, 2010	(800211)
Item 60	May 21, 2010	(830976)
Item 00	iny al, auto	(0307/0)

Item 61	May 26, 2010	(924858)
Item 62	June 21, 2010	(846298)
Item 63	June 22, 2010	(803894)
Item 64		(842255)
Item 65	August 03, 2010	(841450)
Item 66	August 04, 2010	(844065)
Item 67	August 09, 2010	(844426)
Item 68	August 20, 2010	(866862)
Item 69	August 25, 2010	(849769)
Item 70	September 17, 2010	(860255)
Item 71	September 22, 2010	(873930)
Item 72	September 27, 2010	(864992)
Item 73	October 15, 2010	(866198)
Item 74	October 18, 2010	(866661)
Item 75	November 22, 2010	(896275)
Item 76	December 20, 2010	(896276)
Item 77	January 01, 2011	(902333)
Item 78	January 11, 2011	(872428)
Item 79	February 15, 2011	(893691)
Item 80	February 22, 2011 March 21, 2011	(909118)
Item 81	April 25, 2011	(916371) (924850)
Item 82		(924650) (914116)
Item 83 Item 84	April 26, 2011 May 03, 2011	(914110)
Item 85	May 23, 2011	(938056)
Item 86	May 31, 2011	(922844)
Item 87	June 06, 2011	(922997)
Item 88	June 20, 2011	(932928)
Item 89	June 22, 2011	(945424)
Item 90	June 30, 2011	(934167)
Item 91	July 21, 2011	(952653)
Item 92	August 22, 2011	(948927)
Item 93	August 29, 2011	(951041)
Item 94	September 13, 2011	(950784)
Item 95	September 14, 2011	(950565)
Item 96	September 22, 2011	(965370)
Item 97	October 21, 2011	(971409)
Item 98	November 04, 2011	(964458)
Item 99	November 21, 2011	(977566)
Item 100	November 23, 2011	(968460)
Item 101	December 09, 2011	(969950)
Item 102	December 22, 2011	(974874)
Item 103	December 27, 2011	(984336)
Item 104	January 03, 2012	(974525)
Item 105	January 13, 2012	(974982)
Item 106	January 24, 2012	(990634)
Item 107	February 13, 2012	(970831)
Item 108	February 21, 2012	(1010087)
Item 109	March 22, 2012	(1003522)
Item 110	May 22, 2012	(1016478)
Item 111	June 07, 2012	(1001039)
Item 112	June 13, 2012	(1008992)
Item 113	June 22, 2012 July 23, 2012	(1024200) (1031593)
Item 114	July 23, 2012 July 24, 2012	-
Item 115 Item 116	August 03, 2012	(1020870) (1022507)
Item 116 Item 117	August 03, 2012 August 22, 2012	(1022307)
Item 117	September 18, 2012	(1009913)
Item 119	September 24, 2012	(1031013)
Item 120	October 19, 2012	(1040703)
Item 121	October 19, 2012 October 22, 2012	(1041002)
AUGIN AZA	J. 1000 22, 2012	(10003/3)

Item 122	October 31, 2012	(1035340)
Item 123	November 19, 2012	(1045913)
Item 124	November 26, 2012	(1060974)
Item 125	December 06, 2012	(1043323)
Item 126	January 25, 2013	(1052926)
Item 127	March 07, 2013	(1073630)
Item 128	March 13, 2013	(1057629)
Item 129	March 14, 2013	(1074547)

E. Written notices of violations (NOV) (CCEDS Inv. Track. No.):

A notice of violation represents a written allegation of a violation of a specific regulatory requirement from the commission to a regulated entity. A notice of violation is not a final enforcement action, nor proof that a violation has actually occurred.

Date: 0

Citation:

05/21/2012 (1006775)

CN600127468

Classification:

Self Report? NO

[FOP No. O-02250] GTC & STC No. 21 OP

[Pmt 2937/PSD-TX-1023M2] SC 24E PERMIT

30 TAC Chapter 101, SubChapter A 101.20(1) 30 TAC Chapter 101, SubChapter A 101.20(3) 30 TAC Chapter 115, SubChapter D 115.322(4) 30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4)

40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.482-6(a)(1)

5C THSC Chapter 382 382.085(b)

Description:

Failure to equip each OEL with a cap, blind flange, plug, or a second valve. Specifically, Valero failed to equip 4 OELs (Tag Nos. E21460.13 [found on 05/10/10], E21461.43 [found on 05/10/10], RW9918.1 [found on 05/12/10], and QTK-0872 [found on 10/04/10]), in VOC and HAP service, subject to 28 VHP requirements, with a cap or blind flange, as identified in the deviation reports for the reporting periods of 12/08/10-06/07/11and 06/08/11-12/07/11, respectively.

2 Date:

07/25/2012 (1019809)

CN600127468

Self Report? NO

Classification:

Moderate

Moderate

Citation:

30 TAC Chapter 101, SubChapter A 101.20(1) 30 TAC Chapter 101, SubChapter A 101.20(3) 30 TAC Chapter 115, SubChapter D 115.322(4) 30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4)

40 CFR Part 60, Subpart VV 60.482-6 5C THSC Chapter 382 382.085(b) Special Condition No. 23(E) PERMIT Special Condition No. 25 PERMIT Special Term & Condition No. 1 OP Special Terms and Conditions No. 21 OP

Description:

Failure to equip each open-ended valve or line with a cap, blind flange, plug, or second valve. Specifically, Valero Refining - Texas, L.P. discovered thirty-nine open-ended lines from April 18 through July 7, 2011 and fifty-four open-ended

lines from November 10, 2011 to March 14, 2012.

2

Date: **11/30/2012** (1060975)

CN600127468

Self Report? YES

Classification:

Moderate

Citation:

2D TWC Chapter 26, SubChapter A 26.121(a) 30 TAC Chapter 305, SubChapter F 305.125(1)

Description:

Failure to meet the limit for one or more permit parameter

F. Environmental audits:

Notice of Intent Date: 05/20/2009 (759300)

Disclosure Date: 09/13/2010

Viol. Classification: Minor

Citation: 40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.482-1(a)

Description: Failed to have documentation available that stated that all new equipment had been incorporated into the

LDAR program and initially monitored in a timely manner.

Viol. Classification: Minor

Citation: 40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.482-5(b)

Description: Failed to operate the sampling connection system such that the purged process fluid was collected in

accordance with Subpart W.

Viol. Classification: Minor

Citation: 30 TAC Chapter 115, SubChapter D 115.322(4)

40 CFR Part 60, Subpart VV 60.482-6

Description: Failed to cap open ended lines in process units.

Viol. Classification: Minor

Citation: 30 TAC Chapter 115, SubChapter D 115.322(2)

40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.482-7(d)(1) 40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.482-7(d)(2)

Description: Failed to make an attempt at repair or a retest within 5 days, or the final repair within 15 days after the

detection of a leak. Also, there were instances where components were not re-monitored after the initial or

subsequent repair attempts.

Viol. Classification: Minor

Citation: 40 CFR Part 60, Subpart VV 60.482-8

Description: Failed to prevent stains from forming below fugitive piping components that were not accounted for in the

AVO program.

Viol. Classification: Minor

Citation: 40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.482-9(a)

40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.482-9(e)

Description: Failed to repair two valves in the HDS unit that were designated for delay of repair during the process unit

shutdown which occurred in October or December 2007.

Viol. Classification: Minor

Citation: 30 TAC Chapter 115, SubChapter D 115.325(1)

40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.485(b)

Description: Instances were discovered where time between monitoring was less than twice the instrument response

time when a deflection was measured or was faster than physically possible due to the instrument response

time or the time required to move to the next.

Viol. Classification: Minor

Citation: 30 TAC Chapter 115, SubChapter D 115.325(1)

40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.485(b)

Description: Failed to monitor at all of the potential leak interfaces on a control valve.

Viol. Classification: Minor

Citation: 40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.485(b)

Description: Expired calibration gass were used at the 4 applicable leak definitions (500, 2,000, 3,000 and 10,000

ppmv) from 9/15/06.

Viol. Classification: Minor

Citation: 40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.182(d)

Description: Failed to include the pump monitoring results and the number of non repaired pumps in the semi-annual

report for the first half of 2006.

Viol. Classification: Minor

Citation: 40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.487(a)

40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.487(c)

Description: Failed to identify the number of non repaired valves or pumps on 4 previous NSPS VV periodic reports

during the two years prior to the audit.

Notice of Intent Date: 07/26/2010 (873305)

No DOV Associated

Notice of Intent Date: 02/18/2011 (905295)

Disclosure Date: 04/27/2012

Viol. Classification: Major

Citation: 30 TAC Chapter 106, SubChapter X 106.533

Description: Failure to have PBRs for 35 remediation wells, RW57-RW90 and RWQ02

Notice of Intent Date: 07/26/2011 (981728)

No DOV Associated

Notice of Intent Date: 08/07/2012 (1023725)

No DOV Associated

G. Type of environmental management systems (EMSs): $_{\mbox{\scriptsize N/A}}$

H. Voluntary on-site compliance assessment dates:

N/A

I. Participation in a voluntary pollution reduction program:

N/A

J. Early compliance:

N/A

Sites Outside of Texas:

N/A

Texas Commission on Environmental Quality



§	BEFORE THE
§	
§	TEXAS COMMISSION ON
§	
§	ENVIRONMENTAL QUALITY
	5 63 63 63

AGREED ORDER DOCKET NO. 2013-0248-IWD-E

I. JURISDICTION AND STIPULATIONS

On	, the Texas Commission on Environmental Quality ("the
Commission" or "I	'CEQ") considered this agreement of the parties, resolving an enforcement
action regarding Va	llero Refining-Texas, L.P. ("Respondent") under the authority of TEX. WATER
CODE chs. 7 and 26	5. The Executive Director of the TCEQ, through the Enforcement Division,
	t together stipulate that:

- 1. The Respondent owns and operates a petroleum refinery located at 1300 Cantwell Lane, east of Navigation Boulevard, and approximately 0.5 mile north of Interstate Highway 37, northwest of Corpus Christi, Nueces County, Texas (the "Facility").
- 2. The Respondent has discharged industrial waste into or adjacent to any water in the state under Tex. Water Code ch. 26.
- 3. The Executive Director and the Respondent agree that the Commission has jurisdiction to enter this Agreed Order, and that the Respondent is subject to the Commission's jurisdiction.
- 4. The Respondent received notice of the violations alleged in Section II ("Allegations") on or about January 16, 2013.
- 5. The occurrence of any violation is in dispute and the entry of this Agreed Order shall not constitute an admission by the Respondent of any violation alleged in Section II ("Allegations"), nor of any statute or rule.
- 6. An administrative penalty in the amount of Eight Thousand Four Hundred Thirty-Eight Dollars (\$8,438) is assessed by the Commission in settlement of the violations alleged in Section II ("Allegations"). The Respondent has paid Six Thousand Seven Hundred Fifty-

One Dollars (\$6,751) of the administrative penalty and One Thousand Six Hundred Eighty-Seven Dollars (\$1,687) is deferred contingent upon the Respondent's timely and satisfactory compliance with all the terms of this Agreed Order. The deferred amount will be waived upon full compliance with the terms of this Agreed Order. If the Respondent fails to timely and satisfactorily comply with all requirements of this Agreed Order, the Executive Director may require the Respondent to pay all or part of the deferred penalty.

- 7. Any notice and procedures, which might otherwise be authorized or required in this action, are waived in the interest of a more timely resolution of the matter.
- 8. The Executive Director and the Respondent agree on a settlement of the matters alleged in this enforcement action, subject to final approval in accordance with 30 Tex. ADMIN. CODE § 70.10(a).
- 9. The Executive Director recognizes that the Respondent has implemented the following corrective measures at the Facility:
 - a. By March 21, 2012, initiated a project to convert Tank 202 into a storm water tank;
 - b. By April 20, 2012, removed, treated, tested, and properly disposed of contaminated soil and contaminated storm water from the affected area; and
 - c. By November 8, 2012, converted Tank 202 into a storm water tank to hold contaminated storm water to prevent further overflows of the surge tank.
- 10. The Executive Director may, without further notice or hearing, refer this matter to the Office of the Attorney General of the State of Texas ("OAG") for further enforcement proceedings if the Executive Director determines that the Respondent has not complied with one or more of the terms or conditions in this Agreed Order.
- 11. This Agreed Order shall terminate five years from its effective date or upon compliance with all the terms and conditions set forth in this Agreed Order, whichever is later.
- 12. The provisions of this Agreed Order are deemed severable and, if a court of competent jurisdiction or other appropriate authority deems any provision of this Agreed Order unenforceable, the remaining provisions shall be valid and enforceable.

II. ALLEGATIONS

As owner and operator of the Facility, the Respondent is alleged to have to prevent the unauthorized discharge of contaminated storm water into or adjacent to any water in the state, in violation of 30 Tex. ADMIN. Code § 305.125(4), Tex. Water Code § 26.121(a)(1), and Texas Pollutant Discharge Ellimination System ("TPDES") Permit No. WQ0000465000, Permit Conditions No. 2.g, as documented during an investigation conducted on November 6, 2012. Specifically, on April 16, 2012, to prevent the overflow from the surge tank, an estimated 561,000 gallons of contaminated storm water was pumped to an earthen containment area surrounding Tank 201.

III. DENIALS

The Respondent generally denies each allegation in Section II ("Allegations").

IV. ORDERING PROVISIONS

1. It is, therefore, ordered by the TCEQ that the Respondent pay an administrative penalty as set forth in Section I, Paragraph 6 above. The payment of this administrative penalty and the Respondent's compliance with all the terms and conditions set forth in this Agreed Order resolve only the allegations in Section II. The Commission shall not be constrained in any manner from requiring corrective action or penalties for violations which are not raised here. Administrative penalty payments shall be made payable to "TCEQ" and shall be sent with the notation "Re: Valero Refining-Texas, L.P., Docket No. 2013-0248-IWD-E" to:

Financial Administration Division, Revenue Operations Section Attention: Cashier's Office, MC 214 Texas Commission on Environmental Quality P.O. Box 13088 Austin, Texas 78711-3088

- 2. The provisions of this Agreed Order shall apply to and be binding upon the Respondent. The Respondent is ordered to give notice of the Agreed Order to personnel who maintain day-to-day control over the Facility operations referenced in this Agreed Order.
- 3. This Agreed Order, issued by the Commission, shall not be admissible against the Respondent in a civil proceeding, unless the proceeding is brought by the OAG to: (1) enforce the terms of this Agreed Order; or (2) pursue violations of a statute within the Commission's jurisdiction, or of a rule adopted or an order or permit issued by the Commission under such a statute.
- This Agreed Order may be executed in separate and multiple counterparts, which 4. together shall constitute a single instrument. Any page of this Agreed Order may be copied, scanned, digitized, converted to electronic portable document format ("pdf"), or otherwise reproduced and may be transmitted by digital or electronic transmission, including but not limited to facsimile transmission and electronic mail. Any signature affixed to this Agreed Order shall constitute an original signature for all purposes and may be used, filed, substituted, or issued for any purpose for which an original signature could be used. The term "signature" shall include manual signatures and true and accurate reproductions of manual signatures created, executed, endorsed, adopted, or authorized by the person or persons to whom the signatures are attributable. Signatures may be copied or reproduced digitally, electronically, by photocopying, engraving, imprinting, lithographing, electronic mail, facsimile transmission, stamping, or any other means or process which the Executive Director deems acceptable. In this paragraph exclusively, the terms "electronic transmission", "owner", "person", "writing", and "written" shall have the meanings assigned to them under TEX. BUS. ORG. CODE § 1.002.

Valero Refining-Texas, L.P. DOCKET NO. 2013-0248-IWD-E Page 4

5. Under 30 Tex. ADMIN. Code § 70.10(b), the effective date is the date of hand-delivery of the Order to the Respondent, or three days after the date on which the Commission mails notice of the Order to the Respondent, whichever is earlier.

Valero Refining-Texas, L.P. DOCKET NO. 2013-0248-IWD-E Page 5

Valero Refining-Texas, L.P.

SIGNATURE PAGE

TEXAS COMMISSION ON ENVIRONMENTAL QUALITY

	1
For the Commission	
For the Executive Director	8/22/13 Date
agree to the attached Agreed Order on behalf	d the attached Agreed Order. I am authorized to f of the entity indicated below my signature, and I d therein. I further acknowledge that the TCEQ, in materially relying on such representation.
 and/or failure to timely pay the penalty amounts. A negative impact on compliance history. Greater scrutiny of any permit applicated. Referral of this case to the Attorney additional penalties, and/or attorney for a linereased penalties in any future enformation. Automatic referral to the Attorney Great and. TCEQ seeking other relief as authorized. 	ry; ions submitted; General's Office for contempt, injunctive relief, ees, or to a collection agency; cement actions; eneral's Office of any future enforcement actions;
Signature Cy	$\frac{5/24/2013}{\text{Date}}$
Dennis Payne	Vice-President & General Manager
Name (Printed or typed) Authorized Representative of	Title

Instructions: Send the original, signed Agreed Order with penalty payment to the Financial Administration Division, Revenue Operations Section at the address in Section IV, Paragraph 1 of this Agreed Order.